

General Requirements to act as a Spotter

With plant and equipment working in the vicinity of overhead electrical assets

1. A person **must** have a current competency to 'Provide First Aid' (HLTAID011) and
2. A person **must** hold a current competency to 'Provide Cardiopulmonary Resuscitation' (HLTAID009) and,
3. A person **must** have undertaken an approved Spotter training course (22597VIC) (Course in Workplace Spotting for Service Assets) and hold an appropriate Spotters Registration Certificate/Card which is valid for a period of three (3) years.
4. A trained Dogman/Rigger may act as a spotter for any type of plant (without holding a ticket or demonstrate competence and experience for that item of plant), subject to compliance with items 1, 2 and 3 above.
5. For all other plant and equipment, a person must hold a Certificate of Competency or WorkSafe ticket for the item of plant that person will be spotting for; or
 - a. For items of plant such as an EWP <11 metres, or a Vehicle Mounted Crane < 10 tonne/metres and other plant where there is no formal WorkSafe operating competency, some evidence of training, competency assessment and or experience must be demonstrated to the RTO to enable that person to obtain a Spotter Registration Certificate.
6. A person must hold a Licence to drive a 'Light Rigid' (LR) truck or higher (e.g. HC or HR), to be granted the endorsement of 'TT' subject to compliance with Items 1, 2 and 3 above.
7. It should be noted, that a Spotter is required for each item of plant or equipment operating in the vicinity of overhead electrical lines on any work site.
8. Energy Safe Victoria has set the minimum age for a person to be registered as a Spotter with Energy Safe Victoria to be 18 years of age as this aligns with high-risk licence requirements.

Important information

Safe Systems of Work shall be used. It is expected this would include but not be limited to, Permit to Work assessments, Dial Before You Dig enquiries, Job Safety Analysis/Assessments (JSA), Hazard and Risk Assessments and Safe Work Method Statement (SWMS). These must be documented, completed and communicated prior to the commencement of each project, and the Spotter should hold an appropriate copy for the spotting task that is to be undertaken.

A 'Permit to Work in the vicinity of Electrical Apparatus', should be issued by the Electrical Distribution or Traction Company, when work is to be undertaken closer than 3 metres from any overhead electric line.

All work should be undertaken with reference to the following WorkSafe Victoria documents.

- FRAMEWORK FOR UNDERTAKING WORK NEAR OVERHEAD AND UNDERGROUND ASSETS
- GUIDE FOR UNDERTAKING WORK NEAR UNDERGROUND ASSETS
- USING EARTHMOVING EQUIPMENT NEAR OVERHEAD ELECTRICAL ASSETS

July 2022